	Type	Hits	Search Text	
1	BRS	1056	361/42.ccls.	
2	BRS	17	361/42.ccls. and (housing same interrupt\$3 same detection)	
3	BRS	2606	ground same fault same interrupt\$3	
4	BRS	51	(ground same fault same interrupt\$3) and (housing same interrupt\$3 same detection)	
5	BRS	45	("6052265" "5982593" "5966280" "5956218" "5875087" "5825599" "5754114" "5726900" "5715125" "5642052" "5515218" "5481194" "5477412" "5459630" "5363269" "4829289" "4816957" "4292" "585" "4280092" "3932790").pn.	
6	BRS	15	("5266039" "5933063" "5510760" "5943199" "4002951" "4595894" "5594398").pn.	
7	BRS	3	6515564.pn.	
8	BRS	1	"6525541" .pn.	
9	BRS	578	bistable near relay	
10	BRS	511	bistable adj relay	
11	BRS	4	((bistable adj relay) (bistable adj latching adj relay)) same ground same fault	
12	BRS	2	"6349908" .pn.	
13	BRS	2	"6349908" .pn.	
14	BRS	3	"6515564" .pn.	



	DBs	Time Stamp	Comments	Error Definition	
1	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 10:36			
2	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 10:49			
3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 10:48			
4	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 11:51			
5	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 13:09			
6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 13:10			
7	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 13:24			
8	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 13:32			
9	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 13:33			
10	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 13:34			
11	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 13:42			
12	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 13:42			
13	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 15:54			
14	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2003/05/28 15:54			

05/29/2003, EAST Version: 1.03.0007